Attorney Docket No. 121.1002D

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Etsuko HAYASHI, et al.

Application No.: 10/624,568

ATTENTION

Confirmation No.: 6610

CERTIFICATE OF CORRECTION

Filed: July 23, 2003

BRANCH

Certificate

U.S. Patent No.: 6,891,661

FEB 0 6 2006

Issued: May 10, 2005

of Correction

For:

OPTICAL AMPLIFIER WITH PUMP LIGHT SOURCE CONTROL FOR RAMAN

AMPLIFICATION

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents

PO Box 1450

Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date:

Jeh 2 204

Bv:

H. J. Staas

Registration No. 22,010

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005

Telephone: (202) 434-1500 Facsimile: (202) 434-1501

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,891,661 DATED: May 10, 2005

INVENTOR(S): Etsuko HAYASHI, et al.

First Page, Column 2 (Foreign Patent Documents), change "G02F/1/35" to --G02F/135--.

Column 18, line 67, change "In" to --in--.

Column 20, line 50, after "output" delete "power and insert --powers--.

MAILING ADDRESS OF SENDER: STAAS & HALSEY LLP 1201 New York Ave., N.W. Suite 700 Washington, DC 20005 PATENT NO. 6,891,661

No. of add'l copies @ 50¢ per page